

Seat No.: _____

Enrolment No. _____

GUJARAT TECHNOLOGICAL UNIVERSITY
B. E. - SEMESTER – VII • EXAMINATION – WINTER 2012

Subject code: 171903

Date: 01/01/2013

Subject Name: Computer Integrated Manufacturing

Time: 10.30 am - 01.00 pm

Total Marks: 70

Instructions:

1. Attempt any five questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

- Q.1** (a) What are the basic components of numerical control system Draw and discuss function of each component. **04**
- (b) Explain the term “Work Volume “with respect to robots. **03**
- (c) Enlist benefits of flexible manufacturing system. **03**
- (d) Process rationalization and standardization is a benefit derived from CAPP. Explain. **04**
- Q.2** (a) Why is part classification and coding required in GT. Explain OPTIZ system of coding . **07**
- (b) Explain with neat sketch AS/RS system used in FMS **07**
- OR**
- (b) Explain the types of flexibilities in FMS and discuss the factors on which these flexibilities depend. **07**
- Q.3** (a) List the various models of CIM. Explain anyone in detail. **07**
- (b) Explain with neat diagram retrieval type CAPP. **07**
- OR**
- Q.3** (a) What is CIM. Discuss the components of CIM. **07**
- (b) Explain with neat diagram generative type CAPP. **07**
- Q.4** (a) Draw neat sketches and explain various robot configurations. **07**
- (b) Discuss various applications of robots. **07**
- OR**
- Q.4** (a) Explain the commonly used robot programming languages giving examples. **07**
- Q.4** (b) Draw a vertically articulated robot. Explain its working showing work envelope, degree of freedom and discuss its applications. **07**
- Q.5** (a) What are canned cycles? What is the difference between a canned cycle and subroutine ? Discuss how a canned cycle can be useful in writing a part program . **07**
- (b) Write a part program for component shown in Figure.1. **07**
- OR**
- Q.5** (a) What are the different geometric statements used to write part program using APT? Discuss each statement with a suitable example **07**
- (b) Explain with the help of part programming , the concept of subroutine and do loops for programming the component shown in Figure.2 **07**




Figure 1
Dimensions are in mm.




Figure 2
Dimensions are in mm.

MISCELLANEOUS (M) FUNCTIONS

Following is a list of miscellaneous functions used in the milling and turning examples in this text. Other M functions common to General Numeric and FANUC controllers are also listed.

- M00—Program stop.
- M01—Optional stop.
- M02—End of program (rewind tape).
- M03—Spindle start clockwise.
- M04—Spindle start counterclockwise.
- M05—Spindle stop.
- M06—Tool change.
- M08—Coolant on.
- M09—Coolant off.
- M13—Spindle on clockwise, coolant on (on some systems).
- M14—Spindle on counterclockwise, coolant on.
- M17—Spindle and coolant off (on some systems).
- M19—Spindle orient and stop.
- M21—Mirror image X axis.
- M22—Mirror image Y axis.
- M23—Mirror image off.
- M30—End of program, memory reset.
- M41—Low range.
- M42—High range.
- M48—Override cancel off.
- M49—Override cancel on.
- M98—Jump to subroutine.
- M99—Return from subroutine.

Annexure - (II)

PREPARATORY FUNCTIONS (G CODES)

Following is a list of preparatory functions used in CNC milling examples in this text. Other codes commonly used on General Numeric controllers are also listed.

- G00—Rapid traverse positioning.
- G01—Linear interpolation (feedrate movement).
- G02—Circular interpolation clockwise.
- G03—Circular interpolation counterclockwise.
- G04—Dwell.
- G10—Tool length offset value.
- G17—Specifies X/Y-plane.
- G18—Specifies X/Z plane.
- G19—Specifies Y/Z plane.
- G20—Inch data input (on some systems).
- G21—Metric data input (on some systems).
- G22—Safety zone programming.
- G23—Cross through safety zone.
- G27—Reference point return check.
- G28—Return to reference point.
- G29—Return from reference point.
- G30—Return to second reference point.
- G40—Cutter diameter compensation cancel.
- G41—Cutter diameter compensation left.
- G42—Cutter diameter compensation right.
- G43—Tool length compensation positive direction.
- G44—Tool length compensation negative direction.
- G45—Tool offset increase.
- G46—Tool offset decrease.
- G47—Tool offset double increase.
- G48—Tool offset double decrease.
- G49—Tool length compensation cancel.
- G50—Scaling off.
- G51—Scaling on.
- G73—Peck drilling cycle.
- G74—Counter tapping cycle.
- G76—Fine boring cycle.
- G80—Canned cycle cancel.
- G81—Drilling cycle.
- G82—Counter boring cycle.
- G83—Peck drilling cycle.
- G84—Tapping cycle.
- G85—Boring cycle (feed return to reference level).
- G86—Boring cycle (rapid return to reference level).
- G87—Back boring cycle.
- G88—Boring cycle (manual return).
- G89—Boring cycle (dwell before feed return).
- G90—Specifies absolute positioning.
- G91—Specifies incremental positioning.
- G92—Program absolute zero point.
- G98—Return to initial level.
- G99—Return to reference (R) level.